InsHyDe Kick-Off Meeting Agenda (draft_/15/04/2005)

Thursday 21 April 2005

BRE, Watford (UK)

InsHyDe Kick-Off Meeting	
9:30 – 9:45	Welcome. Introductory remarks (NCSRD)
9:45 – 10:00	Short round of personal introduction by each partner (in case all participants have not already met).
10:00 – 10:30	Overall structure of the internal project (NCSRD) and its management
10:30 – 12:30	Consecutive 20 min presentations by the WP18 subtask leaders (subtasks 1 to 10) on goals, structure and link of their subtasks to WPs 1-16.
12:30 – 13:30	LUNCH BREAK
13:30 – 15:00	Consecutive 20 min presentations by the WP18 subtask leaders (subtasks 1 to 10) on goals, structure and link their subtasks to WPs 1-16.
15:00 – 15:15	Coffee break
15:15 – 17:00	Initiation and organisation of work
	Decision on new SBEP for dispersion.
	 Partners CEA, INERIS and FZK present their planned experimental programs
	Initial discussion on experimental – CFD matrix specification
17:00 – 17:30	Next steps (next meetings,)
17:30	Closure of meeting